

# FTI-TLP1 Type 1 - Vehicle Coverage & Preparation Notes

Make	Model	Year	Install	CAN	Lights	RAP	Trunk	I/O Changes
<b>DL-TL2</b>					Park / Auto			Green White/Blue
Lexus	GX460 PTS	2010-17	Type 1	OBD-II	<b>orange</b>			
Lexus	RX350 PTS	2010-15	Type 1	OBD-II	<b>orange</b>			
Lexus	RX 450h pts	2010-15	Type 1	OBD-II	<b>orange</b>			
Toyota	4Runner PTS	2010-19	Type 1	OBD-II	<b>orange</b>			
Toyota	Sienna PTS	2011-17	Type 1	OBD-II	<b>orange</b>			

**Notes:**

**Firmware:** BLADE-AL(DL-TL2, flash module and update starter before installation

**Install:** Type 1 vehicles require use of DL-TL2 firmware and connections marked TL2 (BLADE, Pk Light, and intermediate harness configuration connector), using any other connections labeled TL6 or TL7 will result in malfunction.

**CAN:** The TLP1 harness has multiple configuration options for sourcing vehicle CAN data, this install type requires connection to the CAN source labeled OBD. Do not use the connector labeled BCM.

**Lights:** Parking light control and auto-light handling require connection of the **orange** wire, labeled TL2/TL6 PK LIGHT, to the controller pk light output for status and diagnostic reporting.

**PTS Button:** Idle Mode, a feature which allows the user to exit a running vehicle and enable shutdown control and monitoring by the remote starter, requires a connection to the vehicle PTS button. If this feature is not desired, no connection is made.



**No Takeover:** TL2 operation does not provide secure takeover, the vehicle will shut down upon vehicle entry.

- FT-DAS Required for manual transmission.
- BOTH Red & Red/White MUST be connected with high current application.

**Jumper Setting**


Parking Light	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	(+)Door Trigger In
Accessory	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	(-)Door Trigger In (Default)
Ignition (Default)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Trunk	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Starter
Starter	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Ignition
Parking Light (Default)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Accessory (Default)

**CM7000/7200** Cut loop for A/T

**CM-900S/900AS**

**CM900AS/900S Jumper**




**START  
ACC  
IGN1**



# FTI-TLP1 Type 1 - Installation Notes & Wiring Diagram

- A** Type 1 install requires using the BLADE and PK LIGHT connections marked TL2/TL6, secure unused connections. If vehicle is not equipped with a factory hood pin, connect jumper before programming.
- B** Type 1 installation does not require using the lock connector, please ensure that the unused connector is secured for safety.
- C** This install sources CAN data from the vehicle OBD-II connector, use the connector marked OBD and secure the unused connector for safety.
- D** Type 1 installation uses BLADE-AL(DL)-TL2 firmware and the intermediate configuration jumper marked TL2, using any other jumper will result in malfunction. Secure unused connectors for safety.
- E** PTS connection is required for IDLE MODE (allows user to exit running vehicle, enabling shutdown control and monitoring by the remote starter), connection is not required if this feature is not desired.



**FIRSTECH, L.L.C.**

**OBD-II Connector 1**

**Steering Lock Connector 2**

**Main Body ECU 3**

**PTS Button 4**

**No Takeover:** TL2 firmware operation does not provide secure takeover, the vehicle will shut down upon opening driver's door.

## Module Programming Procedure

- Step 1 - Activate IGN, module LED should blink blue 1x
- Step 2 - Wait, module LED should go solid blue for 2 sec.
- Step 3 - Module programming complete

## LED Programming Error Codes

- Module LED flashing RED during programming
- 1x - CAN error, confirm harness configuration
  - 2x - VIN detection error, confirm configuration and vehicle entry
  - 3x - VIN error, contact support
  - 4x - IMMO learn error, confirm harness configuration
  - 5x - OEM starter detected, see Toyota/Lexus starter locator in the support links section of compustar.idatalink.com
  - 6x - Key vehicle detected
  - 7x - RX error, confirm harness configuration
  - 8x - TX error, confirm harness configuration

## FTI-TLP1 Type 1

SUPPORT - 1(888) 820-3690, EXT. 203