FTI-STP1 Harness Bulletin: Immobilizer Wire

Overview: Production error; immobilizer wire (orange/black) in pin position #4 instead of pin position #5. Although an effort to correct the issue was made, some quantity of harnesses did get shipped before the issue was spotted. We are advising to inspect the harness BLADE connector before attempting to install the harness and program the module.


RSTECH, LLC.

Fig. 2

SUPPORT - 1(888) 820-3690, EXT, 203

ISSUE: Module fails to program to vehicle, will not allow the vehicle to be remote started.

Correction: Step 1.) Locate the orange/black wire and confirm whether it is positioned as illustrated in Fig. 1 or Fig. 2. If the wire is as illustrated in Fig.1, proceed with Step 2 through 5 and complete the repair procedure outlined, if the wire is as illustrated in Fig. 2, correction is not necessary, proceed with harness installation and module programming.



- Step 2.) Using a pick, lightly depress the catch that secures the terminal in the housing then remove the wire and terminal from the housing.
- Step 3.) Using a fine tip razor or utility knfe, inseret the blade beneath the terminal catch and raise it slightly, so that it can be reused to secure the terminal when reinserted into the BLADE connector housing.
- Step 4.) Refer to Fig, 2 for correct position of the orange/black wire (next to brown/red) then reinsert the terminal, pressing lightly until the catch 'snaps' into place, securing the terminal in the connector housing.
- Step 5.) The repair is complete, proceed with installation and programming.



FTI-STP1 Automatic Transmission Application Bulletin/Advisory F

Overview: The **FTI-STP1** harness may require modification for use in **automatic transmission (AT)** applications, some of the product was able to be modified beforre release, but a small quantity was released before being able to be modified internally.


Issue: The FTI-STP1 T-harness has been designed to be compatible with AT (automatic transmission) & MT (manual transmission) applications, but due to a production oversight, the selection mechanism was defaulted to MT mode.

Using a harness configured for an MT application, in an AT equipped vehicle, could result in vehicle module damage, it is advised that the harness be returned to AT mode before installation in vehicles equipped with an automatic transmission.


Correction: Locate the **red/black** (+ Clutch) wire provided in the CN1 connector of the main harness assembly. Cut the **red/black** wire, either flush to the CN1 connector, or leaving enough wire exposed so that you can insulate and secure the ends of the wire that remain after cutting. Insulate each of the remaining ends of the **red/black** wire and secure to prevent any possibility of a short circuit.

If the red/black wire already been disconnected, no further modification is required for AT equipped vehicles.

MODIFICATION REQUIRED FOR AUTOMATIC TRANSMISSION APPLICATIONS ONLY



							CH, LLC. (888) 820-3690, EXT. 203			
Make	Model	Year	Install	CECU/ KAECU	Lights	ECU	POC	I/O Changes		
DL-SUB2 Subaru	WRX PTS AT	2015-18	Type 3A	BFB	Park / Auto DATA	PSUH	N/A	Green White/Blue NONE/NONE		
This installation requires BLADE-AL(DL)-SUB2 firmware, flash module and update the controller firmware before installation. Parking/Diagnostic Lights: Status and diagnostic light control is provided via data, no additional connections required. Type 3 Install: Adapter A (30-pin & 18-pin connectors) is required for this install type. <i>Adapter B (30-pin & 28-pin) is not required.</i> ECU/Junction Connector Locations: BFB: Behind Fuse Box BGB: Behind Glove Box BIC: Behind Instrument Cluster PSUH: Passenger Side Under Hood Automatic Transmission Application I/O Changes: CMX, CM7, and CM9 Series controllers: No configuration changes required. <i>See previous page for modification required</i> <i>at the CN1 connector parking light (+ clutch) output position</i> .										
Type 3 Immobilizer: Immobilizer connection is located at the ECU, located on the passenger side of the engine compartment, and requires modification of the STP1 harness by removing the 35-pin T-section, as illustrated. The white/red & white/black wires can be extended to the ECU location, the white/black wire connecting to the connector side of the wire illustrated. FTI-STP1: Installation and Configuration Notes										
A ADA	APTER A - REQUIRED					•[3OTH Red & Red/Wh	manual transmission. ite MUST be current application.		
B ADAPTER B - DO NOT USE							Parking Light	er Setting		
 MODIFICATION REQUIRED - REMOVE CONNECTOR CONNECTION REQUIRED - BLACK/WHITE CONNECTOR SIDE 								Starter		
E MODIFICATION REQUIRED FOR AUTOMATIC TRANSMISSION								Cut loop for A/T		
	MMOBILIZER DATA O DISARM OEM ALARM O DOOR LOCK O DOOR UNLOCK O		E-BRAKE STATUS DOOR STATUS TRUNK STATUS P/N SWITCH STATUS	VSS STATUS TACH OUTPUT SECURE TAKEOVER	RAP SHUTDOWN	0	START ACC IGN1 IGN1	900S Jumper		



INSTALL GUIDE

B	LADE	
	SERIES	

DOORLOCK INTERFACE

Patent No. US 8,856,780 CA 2759622 COM-BLADE-AL(DL)-SUB2-EN

Page 32 of 34

CARTRIDGE INSTALLATION

Doc. No.: ##75546## 20210416


Slide cartridge into unit. Notice button under LED. 2


Ready for Module Programming Procedure.

MODULE PROGRAMMING PROCEDURE

NOTE

I When programming, only one keyfob will be used. The other one must be located at least 10 feet away from the vehicle.





INSTALL GUIDE



DOORLOCK INTERFACE SUBARU

Patent No. US 8,856,780 CA 2759622 COM-BLADE-AL(DL)-SUB2-EN

Page 34 of 34

Doc. No.: ##75546## 20210416

WARNING: READ BEFORE REMOTE STARTING THE VEHICLE

IMPORTANT

All vehicle doors must be closed and locked prior to remote start sequence. Failure to comply will result in remote starter malfunction.

TAKE OVER PROCEDURE - TO THE VEHICLE OWNER

NOTE

I All vehicle doors must be closed and locked prior to remote start sequence.



TIME RESTRICTI ON COMING UP !



Press UNLOCK on after-market remote.

