FTI-CDP1: Vehicle Coverage and Preparation Notes

F RSTECH,LLC.

50FF0HT - 1(000) 020/3000, EXI, 203											
Make	Model	Year	Install	CAN	Lights	IGN	Hood	I/O Changes			
DL-CH7 Dodge	Journey PTS	2011-17	Type 1	OBD-II	Park / Auto Type A	BCM	BCM	Green White/Blue			

Firmware: Covered vehicles use **BLADE-AL(DL)-CH7**, confirm application, flash module, and update the controller firmware before beginning the installation.


CAN: Type 1 vehicles use CAN connections in harness at OBD-II, the included CAN extension is not required for this install type.

Lighting: Type A parking lights use the 6-pin connector, please ensure that the unused 10-pin connector is properly secured for safety.

Ignition: Common ignition provisions are listed in the BLADE diagram, ignition is also available at the vehicle BCM (connector C5/E, *pink/white*, pin #27).


FTI-CDP1 - Installation and Configuration Notes

- A Required CAN connections.
 - B Not Required.
 - C Hood pin connection (if required).
 - D Ignition jumper, NO CONNECTION required.
 - E Ignition connection.





	FEATURE COVERAGE																		
	0	\bigcirc	0	0	0					0	0	0	0	0	0		\bigcirc	\bigcirc	
BILIZ	PRIORITY UNLOCK	DOOR LOCK	DOOR UNLOCK	ARM OEM ALARM	DISARM OEM ALARM					DOOR STATUS	TRUNK STATUS	RAP SHUTDOWN	BRAKE STATUS	E-BRAKE STATUS	тасн оитрит		SECURE TAKEOVER	PARKING LIGHTS	




INSTALL GUIDE

BLADE	
SERIES	

ALL IN ONE CHRYSLER/DODGE/JEEP/RAM

Patent No. US 8,856,780 CA 2759622 COM-BLADE-AL(DL)-CH7-EN

Doc. No.: ##72396## 20201117




Slide cartridge into unit. Notice button under LED.

2

CARTRIDGE INSTALLATION

Ready for Module Programming Procedure.




INSTALL GUIDE

BLADE	
SERIES	

ALL IN ONE <u>CHRYSLER/DODGE/JEEP/RAM</u>

Patent No. US 8,856,780 CA 2759622



WARNING: READ BEFORE REMOTE STARTING THE VEHICLE

IMPORTANT

I All OEM keyfobs must be at least 10 feet away from the vehicle. All vehicle doors must be closed and locked prior to remote start sequence. Failure to comply will result in remote starter malfunction.

