FTI-GMT3: Vehicle Coverage and Preparation Notes

| F | RSTECH, LLC. SUPPORT - 1(888) 820-3690, EXT. 203 |
|-----|---|
| - 1 | SUPPORT - 1(888) 820-3690, EXT. 203 |

| Make | Model | Year | Install | CAN | Lights | Туре | ВСМ | Configuration | |
|-----------|---------------------------|---------|---------|--------|-------------|------|-----|----------------|--|
| DL-GM12 | | | | | Park / Auto | | | Feature Option | |
| Chevrolet | Silverado 1500 Key AT | 2017-18 | Type 1 | Type A | Type A | Key | LSC | Opt 1-11 to 3 | |
| | w/o OnStar with OEM Alarm | | + Locks | | | | | | |

Firmware: This installation uses BLADE-AL(DL)-GM12, flash module and update the controller firmware before installing.

Install: Type 1 installation sources CAN data from the blue connector of the BCM, requiring the use of the 'A-connector, the connector marked 'B' is not used.

Lights: Type A lights (standard parking lights) are provided, as are **Type H** (hazard lights), both incorporated in the harness for visual display of runtime status/diagnostics. Re-pinning of the CM I/O (gray) harness is required, regardless of which type you choose to use, both options have been provided for your selection. If you choose hazards you will also need to configure the selected POC for one of the following hazard control options, **Hazard1** (POC option #30 (momentary) **or Hazard2** (POC option #23 (latching), depending on hazard switch operation.

Locks: The CM lock connector is mandatory for this installation type. The harness assembly is pre-wired provide the necessary analog control.

ACC configuration: No Onstar/OEM Alarm install requires an ACC pulse with disarm, to properly control the equipped OEM alarm system. Set feature option 1-11 to option 3 (ACC pulse, same timing as disarm pulse)

Lock connector is REQUIRED for this installation type. :)


Configuration of feature option 3-11 to option 3 (ACC pulse, same timing as disarm) is REQUIRED. :)

FTI-GMT3 - Installation and Configuration Notes

- A REQUIRED CONNECTION, SEE NOTE ABOVE
- B REQUIRED CONNECTION
- C REQUIRED CONFIGURATION TYPE A
- D REQUIRED CONFIGURATION KEY TYPE
- **E** REQUIRED SETTINGS CHANGE

| WWWWW. | |
|--|--|
| The American | |
| Z Z | |
| WATER THE | |
| Z Z | |
| The second of th | |
| MMMMM. | |

| FEATURE COVERAGE | | | | | | | | | | | | | | | | | | | | | |
|------------------|--|-----------|-------------|---------------|------------------|--|---------------|--|--|-------------|--|--------------|--------------|----------------|-------------|-----------------|-------------|-----------------|----------------|---------------|--|
| 0 | | 0 | 0 | 0 | 0 | | 0 | | | 0 | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | |
| IMMOBILIZER DATA | | DOOR LOCK | DOOR UNLOCK | ARM OEM ALARM | DISARM OEM ALARM | | 3X LOCK START | | | DOOR STATUS | | RAP SHUTDOWN | BRAKE STATUS | E-BRAKE STATUS | тасн оитрит | DATA/MUX IGN/ST | HOOD STATUS | SECURE TAKEOVER | PARKING LIGHTS | HAZARD LIGHTS | |



(ACC pulse, same timing as disarm pulse)

- 4x No HSCAN activity, check BLUE connector
- 5x No SWC activity, check BLUE connector
- 6x Wrong SWC message, confirm key has been removed 7x No ACC power, check GREEN connector
- 8x No immobilizer data, check GREEN & BLADE connectors 9x - IGN ON, confirm key has been removed
- 10x Keysense active, confirm key has been removed
- 11x No ACC, confirm key is on
- 12x No IGN, confirm key is on
- 13x VIN not matching Weblink data, contact engineering




DOORLOCK INTERFACE
GENERAL MOTORS

Patent No. US 8,856,780 CA 2759622

Page 58 of 59 COM-BLADE-AL(DL)-GM12-EN Doc. No.: ##74801## 20210312

CARTRIDGE INSTALLATION



Slide cartridge into unit. Notice button under LED.

2

Ready for Module Programming Procedure.

MODULE PROGRAMMING PROCEDURE - WITH KLON

