F RSTECH, LLC. SUPPORT - 1(888) 820-3690, EXT. 203

Overview: The initial production release of the FTI-TLK1 harness has an issue where in some vehicles the secondary power input to the CN1 connector will overload the associated vehicle circuit, causing a fuse to blow. This issue affects the initial release of harnesses and is already being addressed in production. A field correction procedure is detailed below in Figure 1.

Issue: The secondary power circuit can overload some vehicle ignition switch circuits, causing a blown 5A/7.5A AM1 fuse, potentially disabling the vehicle and leaving the consumer stranded. Affected adapters are illustrated below in figure 2.

Corrective steps:

- 1.) Select the applicable CN1 adapter, isolate the RED/WHITE power wire, cut wire approximately 4" from the BLACK plug
- 2.) Insulate the wire still connected to the WHITE plug using heat shrink tubing, and strip the insulation on the other wire end
- 3.) Strip a portion of the insulation from the RED wire, attach the stripped RED/WHITE to the exposed RED wire, solder together
- 4.) Apply insulating tape to the soldered connection and secure the cut ends back to the bundle of wires created by the adapter
- 5.) Correction complete, you may safely proceed to finish your installation

Figure 1: Step by step adapter correction





Figure 2: Supplied CN1 Harness Adapters





FTI-TLK1 Type 2B1 - Vehicle Coverage & Preparation Notes

=∥RSTECH,LLC.

SUPPORT - 1(888) 820-3690, EXT. 203								
Make	Model	Year	Install	CAN	Lights	SIL	Locks	I/O Changes
DL-TL5					Park / Auto			Green White/Blue
Toyota Toyota Toyota	Camry 80 bit STD Key Prius C 80 bit STD Key Yaris 80 bit STD Key	2012-14 2012-14 2012-14	Type 2/B Type 2/B Type 2/B	OBD-II OBD-II OBD-II	A / A A / A A		RDA 1 RDA 1 RDA 3	START 2/None

Hey! Read this stuff before you start the installation ...

Firmware: Covered vehicles use BLADE-AL(DL)-TL5, flash module and update the controller firmware before installing.

Install: Type 2A vehicles use the TL5/9 main harness and TL 5/9 B CN1 adapter, using any other adapters will result in malfunction or damage.

Lights: Type A parking lights require a connection between the **green/white** wires in the **park/auto** and **BECU** harnesses. Type A auto lights require cutting the violet **AUTO LT. A** loop on the BECU harness, connecting the loop ends to the **white/red & white/black** wires in the park/auto harness.

Locks: Lock control requires a connection between the harness RDA and RDA 3 wires, secure unused RDA connections for safety.

I/O Changes: Listed vehicles require changing the controller output from **Parking Light** to **START**, CM7x00 controllers move jumper 3 to STARTER position, CM900 controllers set feature option 1-6 to 2. If issues arise disarming the OEM alarm during remote start, set option 1-01 to 2.

Okay, now get to work...

