F RSTECH, LLC. SUPPORT - 1(888) 820-3690, EXT. 203

Overview: The initial production release of the FTI-TLK1 harness has an issue where in some vehicles the secondary power input to the CN1 connector will overload the associated vehicle circuit, causing a fuse to blow. This issue affects the initial release of harnesses and is already being addressed in production. A field correction procedure is detailed below in Figure 1.

Issue: The secondary power circuit can overload some vehicle ignition switch circuits, causing a blown 5A/7.5A AM1 fuse, potentially disabling the vehicle and leaving the consumer stranded. Affected adapters are illustrated below in figure 2.

Corrective steps:

- 1.) Select the applicable CN1 adapter, isolate the RED/WHITE power wire, cut wire approximately 4" from the BLACK plug
- 2.) Insulate the wire still connected to the WHITE plug using heat shrink tubing, and strip the insulation on the other wire end
- 3.) Strip a portion of the insulation from the RED wire, attach the stripped RED/WHITE to the exposed RED wire, solder together
- 4.) Apply insulating tape to the soldered connection and secure the cut ends back to the bundle of wires created by the adapter
- 5.) Correction complete, you may safely proceed to finish your installation

Figure 1: Step by step adapter correction





Figure 2: Supplied CN1 Harness Adapters





FTI-TLK1 Type 3A3 - Vehicle Coverage & Preparation Notes

F RSTECH,LLC.

UV SUPPORT - 1(888) 820-3690, EXT. 203								
Make	Model	Year	Install	CAN	Lights	TPMS	Trunk	I/O Changes
DL-TL9					Park / Auto			Green White/Blue
Toyota	4Runner 80 bit H Key	2020	Type 3/A	BCM	A / B	DKP/35		START 2/None

Hey! Read this stuff before you start the installation ...

Firmware: Covered vehicles use BLADE-AL(DL)-TL9, flash module and update the controller firmware before installing.

Install: Type 3A vehicles use the TL 5/9 A CN1 adapter, using any other adapters will result in malfunction and damage.

CAN: Covered vehicles require the CAN source connection to the BCM source connector, the OBD source is not used.

Lights: Type A parking lights require a connection between the **green/white** wires in the **park/auto** and **BECU** harnesses. Type B auto lights require cutting the black **AUTO LT. B** loop on the BECU harness, connecting the loop ends to the **white/red & white/black** wires in the park/auto harness.

Locks: Lock control requires a connection between the harness RDA and RDA 2 wires, secure the unused RDA 1 & RDA 3 connections for safety.

TPMS: OEM RS control (3X Lock Start) feature requires interrupting the listed TPMS ignition circuits located in the driver kick panel 36-pin connector. In the 4Runner, the wire is *gray*, pin #35, in the white connector, connect as illustrated.

I/O Changes:

CM900S/900AS: START2: Set feature option 1-6-2 (starter output 10A max) If issues arise disarming the OEM alarm during remote start, set option 1-01 to 2.

CM7000/7200: START2: Move CM jumper 3 to Starter position.

If issues arise disarming the OEM alarm during remote start, set option 1-01 to 2.

Okay, now get to work...

