F RSTECH, LLC. SUPPORT - 1(888) 820-3690, EXT. 203

Overview: The initial production release of the FTI-TLK1 harness has an issue where in some vehicles the secondary power input to the CN1 connector will overload the associated vehicle circuit, causing a fuse to blow. This issue affects the initial release of harnesses and is already being addressed in production. A field correction procedure is detailed below in Figure 1.

Issue: The secondary power circuit can overload some vehicle ignition switch circuits, causing a blown 5A/7.5A AM1 fuse, potentially disabling the vehicle and leaving the consumer stranded. Affected adapters are illustrated below in figure 2.

Corrective steps:

- 1.) Select the applicable CN1 adapter, isolate the RED/WHITE power wire, cut wire approximately 4" from the BLACK plug
- 2.) Insulate the wire still connected to the WHITE plug using heat shrink tubing, and strip the insulation on the other wire end
- 3.) Strip a portion of the insulation from the RED wire, attach the stripped RED/WHITE to the exposed RED wire, solder together
- 4.) Apply insulating tape to the soldered connection and secure the cut ends back to the bundle of wires created by the adapter
- 5.) Correction complete, you may safely proceed to finish your installation

Figure 1: Step by step adapter correction





Figure 2: Supplied CN1 Harness Adapters





FTI-TLK1 Type 3B4 - Vehicle Coverage & Preparation Notes

F RSTECH,LLC.

SUPPORI - 1(000) 020-3090, EAL 203								
Make	Model	Year	Install	CAN	Lights	SIL	Trunk	I/O Changes
DL-TL9					Park / Auto			Green White/Blue
Toyota	Sequoia 80 bit H Key	2015-17	Type 3/B	OBD-II	SW 23 / 21	GBX/10	BECU/26	

Hey! Read this stuff before you start the installation ...

Firmware: Covered vehicles use BLADE-AL(DL)-TL9, flash module and update the controller firmware before installing.

Install: Type 3B vehicles use the TL 5/9 B CN1 adapter, using any other adapters will result in malfunction and damage.

CAN: Covered vehicles require the CAN source connection to the OBD source connector, the BCM source is not used.

Lights: Type SW parking lights require direct connection to the vehicle parking light and auto-light circuits, the **green/white** wire in the **park/auto harness** connects to pin #23, **orange**, in the 26-pin connector at the BECU. Type SW auto lights require cutting the **green** wire at pin #21 in the same 26-pin connector, and connecting the cut ends to the **white/red** & white/black wires in the park/auto harness.

Locks: Lock control requires a direct connection between the harness RDA wire and the *violet* wire located in the 28-pin connector, pin #12. Secure all unused RDA connections for safety.

TPMS: The Sequoia requires an interrupt of the SIL data wire at the TPMS module (behind glove box) which opens a necessary communication line. Cut the wire at the TPMS module 12-pin connector, pin #10, *blue*, and connect as illustrated.

Trunk:

Trunk/Hatch release requires additional wiring, connect CM (-) trunk output, or program any available POC for trunk release and connect to the BECU 28-pin connector, pin #12, *violet* wire. If issues arise disarming the OEM alarm during remote start, set option 1-01 to 2.

Okay, now get to work ...

