## FTI-TLK1 Harness Bulletin - Mis-wired Power Circuits



Overview: The initial production release of the FTI-TLK1 harness has an issue where in some vehicles the secondary power input to the CN1 connector will overload the associated vehicle circuit, causing a fuse to blow. This issue affects the initial release of harnesses and is already being addressed in production. A field correction procedure is detailed below in Figure 1.

Issue: The secondary power circuit can overload some vehicle ignition switch circuits, causing a blown 5A/7.5A AM1 fuse, potentially disabling the vehicle and leaving the consumer stranded. Affected adapters are illustrated below in figure 2.

## Corrective steps:

- 1.) Select the applicable CN1 adapter, isolate the RED/WHITE power wire, cut wire approximately 4" from the BLACK plug
- 2.) Insulate the wire still connected to the WHITE plug using heat shrink tubing, and strip the insulation on the other wire end
- 3.) Strip a portion of the insulation from the RED wire, attach the stripped RED/WHITE to the exposed RED wire, solder together
- 4.) Apply insulating tape to the soldered connection and secure the cut ends back to the bundle of wires created by the adapter
- 5.) Correction complete, you may safely proceed to finish your installation

Figure 1: Step by step adapter correction





Figure 2: Supplied CN1 Harness Adapters





## FTI-TLK1 Type 3C3 - Vehicle Coverage & Preparation Notes

	RSTECH, LLC.
1	SUPPORT - 1(888) 820-3690, EXT. 203

Make	Model	Year	Install	CAN	Lights	TPMS	Trunk	I/O Changes
DL-TL9					Park / Auto			Green White/Blue
Toyota Toyota	Highlander 80 bit H Key Tacoma 80 bit H Key	2014-16 2016-17	Type 3/C Type 3/C	OBD-II OBD-II	A/B A/B	BCM/30 BCM/33	· ·	START 2/None START 2/None

Hey! Read this stuff before you start the installation...

Firmware: Covered vehicles use BLADE-AL(DL)-TL9, flash module and update the controller firmware before installing.

Install: Type 3C vehicles use the TL 5/9 C CN1 adapter, using any other adapters will result in malfunction and damage.

I/O Changes:

CM900S/900AS I/O Changes:

START2: Set feature option 1-6-2 (starter output 10A max).

Locks: Configure unlock before and lock after start, set option 1-01 to 2.

CM7000/7200 I/O Changes:

START2: Move CM jumper 3 to Starter position

Locks: If issues arise disarming the OEM alarm during remote start, set option 1-01 to 2.

CAN: Covered vehicles require the CAN source connection to the OBD source connector, the BCM source is not used.

**Lights:** Type A parking lights require a connection between the **green/white** wires in the **park/auto** and **BECU** harnesses. Type A auto lights require cutting the violet **AUTO LT. A** loop on the BECU harness, connecting the loop ends to the **white/red** & **white/black** wires in the park/auto harness.

**Locks:** Lock control requires a connection between the harness **RDA** and **RDA 2** wires, secure the unused **RDA 1** & **RDA 3** connections for safety.

**TPMS:** OEM RS control (3X Lock Start) feature requires interrupting the TPMS ignition circuits located in the following positions:

- \* Highlander BECU 36-pin connector, pin #30
- \* Tacoma BECU 36-pin connector, pin #33 Connect as illustrated.

Okay, now get to work...



